

Oakland Touchdown

Location: 04-Ala-80-1.6/2.7 Client Name: CalTrans **Run date** 16-Feb-13 **Time** 5:56 PM

Daily Diary Report by Bid Item

Contract No. 04-0120L4

Diary #: 248 Const Calendar Day 212 Date: 08-Apr-2010 Thursday Inspector Name: Ghafghazi, Ben Title: Resident Engineer

Inspection Type:

Shift Hours: Break: Over Time:

Federal ID: Location:

Reviewer: Ghafghazi, Ben Approved Date: 20-May-10 Status: Approved

Weather

Temperature 7 AM 12 PM 4PM

Precipitation Condition Clear

Working Day 🗸 If no, explain:

Diary:

Office work

Reprocessed CCO 120-1.

- ·Conducted the weekly scheduling meeting. See meeting minutes for detail.
- Received an email from Lynne Welch of Estimate's desk, supplemental progress pay is ready to be picked up.
- Received action items from our senior staff meeting the other day. My action items are as follows:
- 1.Document Archiving, Due end of April
- 2.Deferred Time CCOs log, Due end of this week.
- 3. Safety attendance log.
- 4. Dumbarton Schedule
- 5. Dumbarton Staffing Plan update
- Received SFOBB Project Summary 4-7-2010 from Keith Huffman, as follows:

Service Platforms - MetalFab, Santa Clara, CA

- Fabrication of service platforms is complete. METS continues to assist Construction with various installation related issues.
- Initial Bolt Samples passed METS QA testing, however subsequent HS bolts were installed without testing, and an NCR has been issued

Roadway Lighting Assemblies - Structural and Steel Products, Fort Worth, TX

- ·4 demonstration light poles have been installed on the skyway.
- •SMR has reviewed and commented on the 95% PS&E submittal. Of particular note is the deletion of the lowering mechanism for the lighting assemblies.

Bike Path Railing - Pisor Fence, Citrus Heights, CA

- ·Fabrication of stainless steel embed base plates is complete
- Fabrication, galvanizing, and painting are complete, and all panels have been installed on the jobsite. Due to damage from improper handling, some repair painting will be necessary.

Bike Path Expansion Joint - MCM Construction, Oakland, CA

- Welding of stainless steel plates is complete
- -Application of non-skid coating to the upper surface, and PTFE strips to the existing plate lower surface has not yet started
- Provided the mole substation diaries to Amer for the period of 12/16/2009 through 1/15/2010.



Daily Diary Report by Bid Item

Job Name: 04-0120L4 Inspector Name: Ghafghazi, Ben Diary #: 248 Date: 08-Apr-2010 Thursday

